



MICHAEL R. STYLER Executive Director JOHN R. BAZA
Division Director

Inspection Report Minerals Regulatory Program

Report Date: August 25, 2005

Supervisor AR

Mine Name: Red Emerald MinePermit number: M/001/045Operator Name: Gemstone Mining Inc.Inspection Date: 6/30/2005Dominique MerzTime: 7:00 – 9:00 p.m.

599 N 800 W #6

Cedar City, Utah 84720 **Inspector(s):** Tom Munson **Other Participants:** none

Mine Status: reclaimed Weather: Sunny

Elements of Inspection	Evaluated	Comment	Enforcement
 Permits, Revisions, Transfer, Bonds Public Safety (shafts, adits, trash, signs, highwalls) Protection of Drainages / Erosion Control Deleterious Material Roads (maintenance, surfacing, dust control, safety) Concurrent Reclamation Backfilling/Grading (trenches, pits, roads, 			
highwalls, shafts, drill holes) 8. Water Impoundments 9. Soils 10. Revegetation 11. Air Quality 12. Other			

Purpose of Inspection: To check the site for full release as requested by the operator.

Inspection Summary:

The Division and the Bureau of Land Management preformed inspections of the mine site in 2005 and determined that the revegetation success found during these inspections allows us to release the site and close the file. Earthwork and the first seeding was completed in late 2001. A partial release of reclamation surety occurred at this time related to the completion of the regarding. The remaining surety of \$9,200 was held to verify revegetation success. This surety is in the form of a TDRA-Bank One #880067493931 which expires on 04/14/2008. Drought conditions resulted in some additional seeding being preformed in early 2003. A site inspection revealed an abundance of Penstamon, Rice Grass, Crested Wheat Grass, and Four Wing Salt Brush. Severe rainfall events have occurred and the earthwork remains stable.

Conclusions and Recommendations:

It is the opinion of the Bureau of Land management as addressed in a letter sent to the Division by Mr. Ed Ginouves on August 15, 2005, that the revegetation had progressed to a point were the site

Inspection Date: June 30, 2005; Report Date: August 25, 2005

Page 2 of 2 M/001/045

can be released. The State requests that the reseeding money left for the site be released which amounts to \$9,200. The State supports this conclusion and recommendation based on this inspection

Inspector's Signature

Date: August 25, 2005

Directions to Site:

The site is located in the Southern end of the Wah Wah Mountains about 17 miles northwest of Lund, Utah. The area has been mined since the late 1970's for red beryl.

TM:jb

cc:

Dominique Merz, GMI, Inc.

Jerry Mansfield, BLM, Fillmore FO

Attachment: Photos